



**Please be advised of a recall that we recently became aware of that may affect officer safety!**

**Description:**

Name of Product

56100 Tactec™ Plate Carriers

The recall involves the 5.11 Tactec Plate Carrier, style number 56100. “5.11” is molded onto a rubber label on the front of the carriers at the bottom left. The style number is printed on a tag in the inside seam of the front pocket. The plate carriers are used by consumers, law enforcement professionals, and first responders in combination with ballistic plates. The plate carrier can also be used for outdoor fitness and weight training and can hold weighted non-ballistic plates. Only carriers with the following PO numbers are included in the recall:

**Hazard:**

The cable in the quick release system of the plate carrier can separate from the handle preventing swift removal of the carrier in an emergency situation, posing an injury hazard.

**Remedy:**

Repair – consumers should immediately stop using the recalled plate carriers and contact 5.11 for a free replacement of the cable system.

**Consumer Contact:**

5.11 Inc. toll-free at 866-451-1726 from 6:30 a.m. to 5 p.m. PT Monday through Friday or online at <https://www.511tactical.com/product-recall> or [www.511tactical.com](http://www.511tactical.com) and click “Contact Us” to email the firm to receive a free replacement cable

Pictures available here: <https://www.cpsc.gov/Recalls/2022/5-11-Recalls-Tactec-Plate-Carriers-Due-to-Injury-Hazard>

**Recall Details:**

Units:

About 45,170